

# US 2200 XC2 - DATA SHEET



Application: Wherever Deep Cycle 6-volt batteries are needed.

Dimensions: 10-1/4 (260)L x 7-1/8 (181)W x 11-1/4 (286)H

**Type:** Flooded Lead Acid (FLA) non-sealed.



Case material: Polypropylene / Heat Sealed

		U	S	2	2	0	D	Х	С	2	SI	PE	CIF	FIC	AT	101	NS	3		
BCI												Standard	AMP	MINUTES	MINUTES	MINUTES				wet
Group	Model	1-hr	2-hr	5-hr	6-hr	10-hr	20-hr	48-hr	72-hr	100-hr	Voltage	Terminal	HOURS	@	@	@	Length	Width	Height	Weight
Size		Rate	Rate	Rate	Rate	Rate	Rate	Rate	Rate	Rate		Туре	(20 HR. RATE)	75 AMPS	56 AMPS	25 AMPS	10-1/4	7-1/8	11-1/4	Lbs (kg)
GC2	US 2200 XC2	133	152	181	187	206	232	246	252	258	6	UTL	232	122	175	474	(260)	(181)	(286)	62 (28)

### **TERMINAL OPTIONS:**



SAE



## **VENT CAP OPTIONS:**





### **CHARGING INSTRUCTIONS:**


RGE


Following is the charging recommendation and charging profile using 2 stage chargers for US Battery deep cycle products. \*Equalization and float charge modes are not considered to be one of the stages in a charging profile.

1. 2.	Bulk Charge Absorption Charge	Constant current @~10% of C/20 Ah in amps to 2.45+/-0.05 volts per cell (e.g. 7.35 volts +/-0.15 volts per 6 volt battery) Constant voltage (2.45+/-0.05 vpc) to 3% of C/20 Ah in amps then hold for 2-3 hours and terminate charge Charge termination can be by maximum time (2-4 hr) or dV/dt (4 mv/cell per hour)							
	<ul> <li>(Optional Float Charge)</li> <li>Equalization Charge</li> </ul>	stant voltage 2.17 vpc (6.51 volts per 6 volt battery) for unlimited time stant voltage (2.55+/-0.05 vpc) extended for 1-3 hours after normal charge cycle (repeat every 30 days)							
	Notes:	Charge time from full discharge is 9-12 hours. Absorption charge time is determined by the battery but will usually be ~3 hours at 2.45 volts per cell. Float time is unlimited at 2.17 volts per cell. Specific gravity at full charge is 1.270 minimum							
	Battery temperature adjustm	reduce the voltage by 0.028 Volts per cell for every 10°F above 80°F, increase by the same amount for temperatures below 80°F.							
	This extra charge helps keep a Manually timed chargers shou	e equalized periodically. Equalizing is an extended, low current charge performed after the normal charge cycle. all cells in balance. Actively used batteries should be equalized once per month. Id have the charge time extended approximately 3 hours. ers should be unplugged and reconnected after completing a charge.							


# **US 2200 XC2 - DATA SHEET**


Deep Cycle 6 -Volt





# EXPECTED LIFE CYCLES VS. DOD (XC, XC2 & AGM)







1675 Sampson Avenue Corona, CA 92879 (800) 695-0945

U.S. Battery Recommended Terminal Torque and Connection								
U.S. Battery Terminal Type	Recommended Torque (in-lb)	R <b>etanchenalee</b> Torque (ft-lb)	Recommended Connection Hardware					
UTL	95-105	7.9-8.8	<sup>1</sup> SS Hexnut with Lock Washer					
UT	95-105	7.9-8.8	<sup>1</sup> SS Hexnut with Lock Washer					
Flat Block	95-105	7.9-8.8	<sup>1</sup> SS Hexnut with Lock Washer					
Dual	95-105	7.9-8.8	<sup>1/6</sup> SS Hexnut with Lock Washer					
DC Marine	95-105	7.9-8.8	<sup>2</sup> SS Hexnut with Lock Washer					
Off-Set "S"	100-120	8.3-10	<sup>3</sup> Zn or SS Bolt w/Hexnut & Lock Washer					
Flag	100-120	8.3-10	<sup>4</sup> Zn or SS Bolt w/Hexnut & Lock Washer					
Large "L"	100-120	8.3-10.0	<sup>4</sup> Zn or SS Bolt w/Hexnut & Lock Washer					
Small "L"	100-120	8.3-10.0	<sup>4</sup> Zn or SS Bolt w/Hexnut & Lock Washer					
Bus Lug	120-180	10.0-15.0	<sup>5</sup> SS Hexnut with Lock Washer					
SAE	50-70	4.2-5.8	<sup>6</sup> No Hardware Supplied					
Drepar connection is to position a look weapor between the put and the connector								

Proper connection is to position a lock washer between the nut and the connector (never between the connector and lead terminal) and apply the recommended torque or enough torque to completely compress the lock washer without deforming the lead terminal.

 Stainless Steel Hexnut with Stainless Steel Split-Ring Lock Washer (5/16" Positive & Negative)

 <sup>2</sup>Stainless Steel Hexnut with Stainless Steel Split-Ring Lock Washer (3/8" Positive & 5/16" Negative)

 <sup>3</sup>Square-Head, SS or Zinc-Plated Bolt with SS or Zinc-Plated Hexnut & Split-Ring Lock Washer

 <sup>4</sup>Square-Head or Hex-Head, SS or Zinc-Plated Bolt with SS or Zinc-Plated Hexnut & Split-Ring Lock Washer

 <sup>4</sup>Stainless Steel Hexnut with SS split-Ring Lock Washer (1/2" Positive or 3/8" Positive & 3/8" Negative)

 <sup>5</sup>Stainless Steel Hexnut with SS Split-Ring Lock Washer (1/2" Positive or 3/8" Positive & 3/8" Negative)

 <sup>6</sup>No Hardware Supplied - Application Uses SAE Clamp for Positive & Negative Post

Note: The use of flanged nuts and other types of nuts with captive washers or other hardware not listed above is not recommended by US Battery and their use may void the battery warranty.

# US 2200 XC2 DISCHARGE TIME VS CURRENT @80° F

### U.S. Battery Operating Temperature Guidelines

For charging, we recommend staying within 0°F to120°F (-18 to 49°C) to avoid charging frozen batteries at low temperature or going into thermal runaway at high temperature.

*For discharging*, we recommend -20°F to 120°F (-29 to 49°C). Batteries discharged at temperatures below 32°F (0°C) should be recharged immediately to avoid freezing.

# Batteries discharged at temperatures above $120^{\circ}F$ (49°C) should be allowed to cool before recharging.

Extreme temperatures can substantially affect battery performance and charging. Cold reduces battery capacity and retards charging. Heat increases water usage and can result in overcharging. Very high temperatures can cause "thermal run-away" which may lead to an explosion or fire. If extreme temperature is an unavoidable part of an application, consult a battery/charger specialist about ways to deal with the problem.

Data references within this publication are nominal and should not be considered or construed as maximum or minimum values for specifications or for final design. Data for this product type and model may vary from what is shown in this publication, and U.S. Battery Mfg., Co. makes No warranties, expressed or implied based on the data within this publication.

©2013 U.S. Battery Mfg., Co. All rights reserved. U.S Battery is not liable for damages that may occur from any information provided in or omitted from this publication, under any circumstances. U.S. Battery Mfg., Co. reserves the right to make changes or adjustments to this publication at any time without notices or obligations.

> 1895 Tobacco Road Augusta, GA 30906 (800) **522-0945**

717 North Belair Rd. Evans, GA 30809 (888) 811-0945

# For more information or questions, please visit **WWW.USBATTERY.COM**

©2013 U.S. Battery Mfg., Co. All rights reserved.